


Temperature and humidity

Setting the temperature up to 25 ~65 °C and humidity up to 60 ~90% can be easily set.
 The cycle operation function can be added by the temperature and humidity program for high temperature specification (up to 85 °C) !
 Also, no condensation because it is a full duplex tank!




Temperature and Humidity Control Range Diagram



Gas Concentration

Flow can be set easily by a dial!
 Gas concentration 10 ppb~500 ppm
 Gas flow 0~10 ccm/min



It is also possible to control gas concentration automatically by loading a gas analyzer which is an option.

Automatic control system

